Traffic Signal Head Backplates

North Carolina Department of Transportation Division of Highways


Traffic Signal Technician / Contractors
Conference

April 10 - 11, 2007

presented by: Greg A. Fuller, PE

What is a backplate?

MUTCD - A thin strip of material that extends outward from and parallel to a signal face on all sides of a signal housing to provide a background for improved visibility of the signal indications.



MUTCD Standard

NONE

MUTCD Guidance (Section 4D.17)

- The use of a signal backplate for target value enhancements should be considered on signal faces viewed against a bright sky or confusing backgrounds.
- The use of backplates enhances the contrast between the traffic signal indications and their surroundings for both day and night conditions, which is also helpful to elderly drivers.

ITS and Signals Design Manual Requirements

None

(Engineering Judgement - Division and Regional Traffic Engineers)






Maintenance Issues

- Damaged Backplates (Bent / Missing Pieces)
- Missing Backplates
- Increased Loading (Increases Metal Pole Support Size)
- Signal Heads more prone to movement during high winds.















US 264 Alternate




Three tightly spaced signalized intersections (approx. 1/3 mile segment).



US 264 Alternate (First Signal) (No Backplates Eastbound)





US 264 Alternate (Second Signal) (One Backplate Eastbound)





5 Phase **Fully Actuated** (Wilson-US 264 Alternate Closed Loop Signal System)

MOTES

- 1. Refer to "Roadway Standard Drawings NCDOT" dated January 2002 and "Standard Specifications for Roads and Structures" dated January 2002.
- 2. Do not program signal for late night flashing operation unless otherwise directed by the Engineer. 3. Pavement earkings are existing.
- 4. Deit phase 1 during phase 2 on-
- 5. Omit phase 5 during phase 6 on.
- 6. Maximum times shown in timing chart are for free-run operation only. Coordinated signal system filling
- values shall superseds these values-7. Run new lead-in cobie to each of the following loops: 2A, 29: 6A and 68. Mire mose loops to separate detectors.
- 8- Set all detector units to presence mode.

LEGEND

Sraffin Signal Book

Modified Signot Reed

Sign Signal Pale with Gay Signal Pole with Sidewalk Buy

Industive Loop Detector Controllier & Cobinet Junction Box

2-In Inderground Contuit Right of May Directional Arrow

Personnt Marking Arrow

9- Closed loop system date: Controller Asset #1008.

2070			L DET	El	CTO	R	IJ	48	T۷	VLLA	TIO	į		
10	MDUCTI	VE LO	95		Of	П	ZT.	OR	P	XXXX	MING	1 1		
unor	303 PT	Hera.	DETAILS DETAIL PO	100 100	-	Compag	BIRMON	FOL. THE 25A	STORY GOOD	manos Sed	BEAUT Tools	ı.		
18.	2-00	2-4-2	+5		6	Υ	T	п	-	-	3.	7		
10.	6000	2-4-2	+4	2	T.	Υ	T	-	-		1.5	1		
24	Soci	DESTIN	300	-	2	Υ	ř	-	-	-	-	Ħ		
26	Social	DESIDE	300		2	Υ	Υ	=		- 1	- 11	4		
44.	6a.40	2-4-2	+5	-	.4	Υ	Ŧ	-	-	-	3.	T		
46	6#60	2-4-2	+5	-	4	Υ	T	-	-	-	10	¥		
54	6=50	2-4-2	+5		2	Υ	ï		-	-	3	¥		
26	6860	5-4-5	*5	."	5	Υ	Ÿ	Ε.			15	7		
SA	5x6	DESTRU	300	-	6	Υ	Ŧ	Ε,	-	-	-	T		
68	55.5	HAMP	300	-	6	т	r	-	-	-	-	٦		
3A	6440	2-4-2	+5	-	8	Υ	ř	-	-	-	1	1		
60	6460	2-4-2	45	-	0	Υ	Ŧ		-	-4	10	4		

TABLE OF OPERATION FACE 22,23 8 8 8 8 9 8 41, 42 62 B G B G B Y BLB2 RRRRGR

SIGNAL FACE I.D. O Demotes L.E.D.

22, 37

PRACTIC DEAGRAM DETECTION LEGERS

PHASING DIAGRAM


22+6

8215

DETECTED MOVEMENT INDETESTED BOVENEST (OVERLAP)

DISTRIBUTED NOVEMENT 4----

PEDESTRUM NOVEMENT



	20	070L TIM	IING C	HART				
	PHARE							
PIATURE	1	2	4		+			
Min Green 1 *	- 2	12	3	1	12	T		
Selection 1 *	1.0	6.0	3.0	1.0	6.4	LG		
Mar Green 1 *	15	10	20	18	80	20		
Yellow Cherence	4.0	4.7	4.0	4.0	4.2	4.0		
Red Chorence	2.0	5.0	1.5	2.0	1.0	2.8		
No. 1"	-	- 1	-	-	-	-		
DuniYWsh 1	-	-	-	-	-	-		
Sounds For Autoritor *	-	1.6	-	-	1.5	-		
Max Redubble tollar?		34			34	7.		
line below between "	-	15 .	-	-	18	-		
New To Balton 1	-	30	-	-	30	-		
Minimum Cop	-	3.0	-	-	5.8	-		
Result Mode	-	MON ROOM.	-		NBM POSAUL	- 2		
Nobble Cell Nemon		HOULOW	-	-	ASTYON	-		
Day Supp	-	-	661	-	-	DH		
Smulteress Day	OB	ON	991	-004	894	104		

* Dazar values may be fall indipated. Do not subject this Green and Edwardon Steen to phones 2 and 6 breen than what is chosen. Alls Green for all other phones absolut makes become them 4 seconds.

PLAN QUANT	LITIES		
Pay Stee	Fort		
Ragnell Codice	510		
Bessenger Dabbe			
Lond, in Sable	4.2/50		

Signal Upgrade

US 264 Alternate (Maleigh Moad) at Wal-Mart/Harris Teeter

PROPOSED

0--

180

D

Full Parter Street et

EXTRIBU

M/A

 \rightarrow

US 264 Alternate (Third Signal) (All Backplates Eastbound)



Backplates on Metal Poles



- Backplates are a major factor on the sizing of metal poles.
- Not so much the additional weight, but rather the additional wind surface area.
- Might require 20 -30 % increased strength of metal pole.

Backplates on Signal Plans

- If the traffic signal plan requires backplates, backplates must be present.
- If the traffic signal plan does not require backplates, then the installation of backplates goes beyond the minimum requirements of the traffic signal plans.
- Do not install backplates on metal poles unless shown on the traffic signal plan or unless a structural analysis has been performed.

Retroreflective Border on Signal Backplates



- FHWA issued interim approval on February 6, 2002.
- Approval is for use of a yellow retroreflective strip between 1 to 3 inches wide around the perimeter of the backplate.
- A written request for approval must be submitted to the FHWA.
- NCDOT has <u>NOT</u> sought interim approval for use along the State Highway System.
- Thus, <u>NOT</u> currently approved for use on the State Highway System.

Conclusion

- Field verify that backplates are necessary (sun glare, cluttered background, etc.).
- Be consistent in the application of backplates, especially along a corridor and on an intersection approach.
- Maintain backplates by replacing / repairing as necessary.
- If backplates do not exist but are required on the plans, take corrective action.

For Additional Information Contact:

Mr. Greg A. Fuller, PE
Telephone: (919)733-8021
E-mail: gfuller@dot.state.nc.us